


August 1, 2005

To: AST Customers
Re: Possible Antenna Issues

It has come to our attention that a small portion of antenna cables may have been shipped with the incorrect pin configuration. In most cases the system will not respond and the LEDs on the antenna will stay on continuously. We are currently doing our best to check all cables before shipping. If you are experiencing this problem check the pictures below for the correct pin configuration.



If you have any further questions please do not hesitate to contact me.

Thank you,
Terry Thompson
Technical Support Manager
Applicated Security Technologies
866 698 5872 ext.302
e-mail t.thompson@ultrastarters.com
web www.ultrastarters.com