



November 8, 2005

To: AST Customers  
Re: DL-3 Door Lock Module

It has come to our attention that a small portion of the DL-3 door lock modules may have been shipped with the incorrect pin configuration. This model will not function with this incorrect configuration. If you are experiencing this problem check the pictures below for the correct pin configuration. We are currently doing our best to check all the harnesses for this product and apologize in advance for any inconvenience.



**Correct Pin Configuration**  
Pin #1 Purple  
Pin #2 Brown  
Pin #3 Blue  
Pin #4 Green  
Pin #5 White



**Incorrect Pin Configuration**  
*Pin #1 White*  
*Pin #2 Green*  
*Pin #3 Blue*  
*Pin #4 Brown*  
*Pin #5 Purple*