

May 28, 2003

Re: 430/ 440 Series alarms

It has come to my attention that in some cases when adding a relay to convert the park light output of the unit to negative output, the module will act erratically. The internal park light relay as well as the added external relay will “Buzz” or chatter. If this situation is encountered a diode must be added between the coil pins of the relay. (See Below)

Typical positive to Negative Park light relay

